

CORNER RECORD


2007-1153A

Document Number _____

City of LAGUNA BEACH County of ORANGE, California

Brief Legal Description CENTER LINE INTERSECTION OF CARMELITA STREET AND AGATE STREET

COORDINATES (Optional)



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other

Date of Survey _____

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vertical Datum: NGVD29 NAVD88
 Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
FOUND REBAR, DOWN 0.1'

THE PURPOSE OF THIS SURVEY WAS TO TIE OUT MONUMENT PRIOR TO PAVEMENT REHAB PROJECT.

A description of the physical condition of the monument as found and as set or reset: SEE PAGE 2.
FOUND REBAR ON ACCEPTED AS CENTERLINE INTERSECTION OF CARMELITA STREET AND
AGATE STREET. NO REFERENCE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on JULY 5, 2007

Signed [Signature] (P.L.S.) or R.C.E. No. 8072




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 25 2007
 examined and filed AUG 17 2007

Signed [Signature] (P.L.S.) or R.C.E. No. 7212
 Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



- △ FOUND REBAR, DOWN 0.1', NO REF.
- SET CHISELED "X" ON CONCRETE FIRE HYDRANT PAD
- SET PK
- ▣ SET NAIL ON SIDE OF POWER POLE # 23101



N.T.S.

NOTE: ALL TIES ARE TEMPORARY. PERMANANT TIES WILL BE SET AFTER CONSTRUCTION.