


CORNER RECORD

Document Number 2007-1148A

City of LAGUNA BEACH County of ORANGE, California

Brief Legal Description CENTER LINE INTERSECTION OF AGATE STREET AND GLENNEYRE STREET



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey MARCH 19, 2007

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation. _____
 Vertical Datum: NGVD29 NAVD88
 Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND SPIKE & WASHER "L.S. 4653"

THE PURPOSE OF THIS SURVEY WAS TO TIE OUT MONUMENT PRIOR TO PAVEMENT REHAB PROJECT.

A description of the physical condition of the monument as found and as set or reset: SEE PAGE 2.

THE INTERSECTION OF GLENNEYRE ST. AND AGATE ST. IS SHOWN ON PARCEL MAP 58/24.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on JULY 5, 2007

Signed [Signature] P.L.S. or R.C.E. No. 8072



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____


examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____





- △ FOUND SPIKE & WASHER "L.S. 4653", NO REF., ACCEPTED AS CENTERLINE INTERSECTION.
- SET CHISELED "X" ON TOP "X"
- SET "C" NAIL
- ⊙ FOUND NAIL & TAG "L.S. 3047" ON TOP OF CURB, NO REF.



N.T.S.

NOTE: ALL TIES ARE TEMPORARY. PERMANANT TIES WILL BE SET AFTER CONSTRUCTION.